

October 29, 1990 590-1157-0100

Mr. James F. McMullin Attorney & Counselor at Law 835 Paul Brown Building 818 Olive Street St. Louis, Missouri 63101

Dear Mr. McMullin:

Enclosed is a copy of the report prepared by Environmental Science & Engineering, Inc. (ESE) for Waste Advisory, Inc. characterizing the PCB contamination at the Thompson Facility.

As stated in the report, additional work is necessary to fully characterize the site and set limits on the areal extent of the contamination. The additional testing is best performed after the area has been sealed and cleaned. The cleaning should consist of the removal of all miscellaneous debris, dirt and dust, followed by wet sweeping and moping the entire area. All work must be performed by OSHA health and safety trained individuals with appropriate protective equipment.

The potential for the migration of PCBs contamination via the floor drain is also an area of concern. If possible, water and/or sediment samples should be collected and tested for PCBs at the point at which the facility effluent meets the metropolitan sewer system. If no contamination is discovered, the EPA may accept removal of the floor drain trap and capping of the remaining pipe with concrete. Solvent flushing of the contaminated pipe may be an option if an appropriate catchment point can be located.

It may be possible to remediate the PCB-contaminated concrete by solvent washing. If this approach does not completely remove the contamination, the EPA may accept encapsulation of the residual PCBs if it can be proved that the PCBs have not migrated through the concrete and impacted the underlying soils.

I wish to emphasize to all parties concerned with the Thompson Facility that the environment in the transformer room is unsafe and contains high levels of toxic particulate matter. The particle material, in part consisting of fine dust, offers an easy exposure route to individuals entering or working in the effected area. In all but the EPA study at the Thompson Facility, the PCB Aroclor 1260 has been the only



11 4 2 3 3 7 3

S00072941 SUPERFUND RECORDS

		_

Mr. James F. McMullin October 29, 1990 Page 2

compound discovered. The Aroclor 1260 (60 percent chlorine) is one of the most toxic compounds commonly discovered at PCB sites.

The NIOSH TWA maximum for the Aroclor 1260 is 1.0 ug/m³, or 1 part per billion per cubic meter. The data gathered in the ESE study strongly suggests that this level could easily be exceeded in the transformer room environment.

It should also be noted that the potential exists for other compounds to be present in the contaminated area. Although rare, and usually associated with high temperature process, the following compounds have been discovered at PCB sites: polychlorinated naphthalenes, polychlorinated dibenzofurans, and polychlorinated dibenzo-o-dioxins. These are some of the most toxic compounds known and should be tested for before remediation work begins.

As soon as possible, the transformer room should be sealed and entry should only be allowed to individuals with a minimum of Class C protective equipment (i.e., Tyvek coveralls, booties, gloves and respirator).

If you have any questions concerning the Thompson Facility please call Wilson Powell of Waste Advisory, Inc. or me.

Sincerely,

Latte Demo

Scott E. George Associate Geologist

djw:c-wt50-s5/cc

cc: Wilson Powell--Waste Advisory, Inc. (w/o)
Jim Owen--Buechner, McCarthy (w/o)

E. William Bergfeld, Jr.-Boatmen's National Bank

		•
		_

PCB CONTAMINATION STUDY

Submitted to:

THOMPSON FACILITY St. Louis, Missouri

Submitted by:

ENVIRONMENTAL SCIENCE & ENGINEERING, INC. St. Louis, Missouri

ESE No. 590-1157-0100

October 1990



Environmental Science & Engineering, Inc.

TABLE OF CONTENTS

Section		Page
1.0	INTRODUCTION	1
2.0	SITE HISTORY	1
	2.1 INITIAL EVALUATION 2.2 CONCRETE REMOVAL	1
	2.3 INSPECTIONMDNR	1
	2.4 REMEDIATION VERIFICATION STUDY	3
	2.5 DUST AND SOIL REMOVAL	3
	2.6 EPA STUDY	3
	2.7 WASTE ADVISORY, INC. STUDY	3
3.0	ESE STUDY	4
	3.1 SURFACE WIPES	4
	3.2 FLOOR DRAIN SAMPLE	5
	3.3 DUST SAMPLE	6
	3.4 CONCLUSIONS	6

APPENDICES

A.	Environmental Operations, Inc.'s Initial Study
В	USEPA Letter Concerning MDNR Inspection
С	Laboratory Data from the Environmental
	Operations, Inc. Remediation Verification Study
D	Laboratory Data from EPA Sampling
E	Waste Advisory, Inc. Report
F	Laboratory Report from the ESE Study
G	Site Photographs from the ESE Study

		,
		i

1.0 INTRODUCTION

This report presents the results obtained by Environmental Science & Engineering, Inc. (ESE) during its investigation of polychlorinated biphenyls (PCBs) contamination at the former Carter Carburetor facility, 2800 North Spring, St. Louis, Missouri. The objective of this investigation was to determine the extent of PCB contamination, review the results of previous studies, and evaluate the site in respect to remediation options and costs.

2.0 SITE HISTORY

The environmental sampling and remediation work performed in the transformer-circuit breaker area to date are summarized in Table 2-1 and described in the following sections.

2.1 INITIAL EVALUATION

An initial evaluation of the site was performed by Environmental Operations, Inc. (EO) in January 1989. According to the EO report (Appendix A) six high level transformers and 16 oil-cooled circuit breakers were located in the study area. The results of four standard wipe tests performed at that time indicated very high levels of PCB contamination [i.e., sample .1 = 106,071 micrograms per 100 square centimeters (ug/100 cm²)] (See Appendix A). Only the PCB 1260 Aroclor was identified in this study.

2.2 CONCRETE REMOVAL

Mr. Hugh Thompson, the present operator of the site, arranged for the removal of the PCB containing transformers and removed most of the visibly oil stained concrete. The contaminated concrete was placed in drums onsite for later disposal (Photograph 4). The removal operation was conducted "dry" (i.e., with a jackhammer). Date is unknown.

2.3 INSPECTION--MDNR

Mr. Henry Rompage Esq. of the USEPA Region VII office stated in a letter dated June 7, 1989 to Mr. James C. Owen, Esq. that an inspection was conducted of Mr. Thompson's facility on February 21, 1989 by Mr. Robert Krager of the Missouri Department of Natural Resources (Appendix B). A soil sample collected from the area where the concrete pad had been removed showed the presence of 1,200 parts per million (ppm) PCBs. No other information is available on this inspection.

				_
				1
				· ·

Table 2-1. Summary of Environmental Sampling and Remediation Work Performed at the Former Carter Carburetor Site

January	1989	A preliminary investigation was performed by Environmental Operations, Inc.
	1989	Heavily contaminated concrete was removed by the present operator.
February	1989	A site inspection and soil sampling was done by the MDNR.
	1989	Additional soil was removed by the present operator.
November	1989	A remediation verification study was conducted by Environmental Operations, Inc.
April	1990	Soil and wipe samples were collected by the USEPA Region VII.
May	1990	A site inspection with concrete sampling was performed by Waste Advisory, Inc.

Source: ESE, 1990.

		_
		_ ′

2.4 REMEDIATION VERIFICATION STUDY

Environmental Operations, Inc. conducted sampling and analysis to determine the effectiveness of the remediation effort (Appendix C). This project, conducted in November 1989, discovered contamination remaining on the surrounding concrete and in the soil underlying the concrete (see Map, Appendix C). The soil levels ranged from 167 to 209 ppm, the levels on the surrounding concrete surfaces ranged from 449 to 5,407 ug/100 cm². Again, only the PCB 1260 Aroclor was identified. The soil contamination may have been due to concrete dust and fragments generated during the removal operation. Several cores of the concrete were taken in the study area during this project. The cores indicated approximately 1/4 inch to 1/2 inch penetration of oil into the concrete. No further testing or analysis was performed on the cores.

2.5 DUST AND SOIL REMOVAL

Mr. Hugh Thompson (operator) removed the concrete dust and some soil in the subject area and placed this material in drums onsite for disposal. Date is unknown.

2.6 EPA STUDY

The United States Environmental Protection Agency Region VII conducted sampling and analysis of the soil and concrete in April and May, 1990. The location of the sampling points is unclear but the report (Appendix D and Photograph 3) indicates that the total PCB concentration in the soils exposed in the concrete removal area range from 17.2 to 18.5 ppm. The wipe samples (exact sampling locations unknown) indicate PCB concentration ranges on the solid surfaces (concrete) from 2.1 to 15,600 ug/cm². Unlike the two early studies conducted by EO which identified only the 1260 Aroclor, the EPA analysis identified a broad range of Aroclors [i.e., 1221 to 1260 (see Appendix D)].

2.7 WASTE ADVISORY, INC. STUDY

In May 1990, Waste Advisory, Inc. along with Brucker and Associates, Ltd. inspected the site and collected three concrete samples from the transformer-circuit breaker area (see Appendix E). The results indicated PCB (1260 Aroclor) concentrations of 225,197, and 82 ppm.

	•		
			<i>,</i>

3.0 ESE STUDY

Environmental Science & Engineering, Inc. (ESE) was contracted by Waste Advisory, Inc. in September 1990 to:

- 1. Determine the concentration of PCBs on the concrete in and around the transformer-circuit breaker area;
- 2. Determine if the PCB contamination had migrated into the adjacent floor drain; and
- 3. Determine if the dust created during the PCB contaminated concrete removal project has contaminated surfaces in the transformer area.

3.1 SURFACE WIPES

On September 6, 1990 Mr. Scott George of the ESE staff collected 18 wipe samples in and around the transformer-circuit breaker area. The sampling method, as outlined in April 12, 1987 Federal Register 40 CFR Part 761, PCB Spill Cleanup Policy; Final Rule, Section III--Definitions (15) Standard Wipe Test, consisted of wiping a hexane saturated gauze pad over a 100 square centimeter area as outlined by a template (Photographs 1 and 2). Individual templates were used at each sampling site. The hexane wipes were prepared in the laboratory and sealed in glass vials until they were used in the field. Strict decontamination methods were used in the field to prevent cross contamination between samples. One blank sample subjected to field conditions was analyzed for PCBs. One set of sampling replicates (Samples 16 and 17) was collected. Standard and accepted chain-of-custody seals and forms were used. Laboratory quality control is documented in Appendix F, Section 2.

The study area was cleaned of miscellaneous debris and swept clean. The debris and dust was placed in piles for later removal. The individual sampling locations were again swept and gently wiped with a damp cloth to remove any remaining dust. Individual templates were taped to the concrete at each sampling location before sampling started (Photograph 1).

The following is a list of results obtained during the ESE study (see Appendix F and Figure 3-1):

			<u> </u>
			_'

Sample ID	Concentration (ug/100 cm ²)
Wipe 1	25.3
Wipe 2	743
Wipe 3	44.1
Wipe 4	535
Wipe 5	190
Wipe 6	1,190
Wipe 7	97.1
Wipe 8	2,520
Wipe 9	6 20
Wipe 10	379
Wipe 11	191
Wipe 12	547
Wipe 13	3 2.4
Wipe 14	74.3
Wipe 15	338
Wipe 16	342
Wipe 17	213
Dust Wipe	31.0
Blank	< 1.40

Note: Only PCB Aroclor 1260 was identified in this study.

As can be seen from this list and Figure 3-1, the concentration of PCBs drop as you move outward from the concrete removal area (former transformer area). It is also apparent that all areas tested exceed the cleanup guideline of 10 ug/100 cm² (see Section 3-4).

3.2 FLOOR DRAIN SAMPLE

A Teflon bailer was used to collect a water sample from the floor drain located adjacent to the west wall (see Figure 3-1 and Photograph 3). The Teflon bailer was thoroughly decontaminated in the laboratory with a soap/water wash, a deionized water rinse, several hexane rinses, and a final deionized water rinse. The bailer was wrapped in aluminum foil until used in the field.

Water is visible in the drain approximately 2 to 3 feet below floor level. Water depth is approximately 6 to 10 inches before the piping turns, either a 90° turn or elbow. The water had a high level of suspended solids and an "oily" appearance. The laboratory results indicated a concentration of 1,620 ppm of PCB Aroclor 1260 in the water. This area will require some form of remediation.

3.3 DUST SAMPLE

A wipe sample of (concrete) dust was collected from a concrete pad approximately 30 feet from the edge of the removal area (see Figure 3-1). The sampling procedure was identical to the methods used for the other wipe samples. The laboratory results indicated 31.0 ug/100 cm² in the sample area. The above results and the presence of white dust (presumably concrete) in the study area indicates extensive cleanup will be required.

3.4 CONCLUSIONS

The ESE study indicates extensive PCB contamination remains in the subject area. This confirms work done earlier by Environmental Operations, Inc.; Missouri Department of Natural Resources; United States Region VII EPA; and Waste Advisory, Inc. Including the present ESE study, a total of six projects have discovered high levels of PCB contamination at the site. Some of this contamination has been removed, but high levels still remain on site.

The ESE study, following well documented procedures and quality control-quality assurance methods, has confirmed the following:

- 1. The concentration of PCBs on the concrete floors in the subject area exceeds the regulatory cleanup levels;
- 2. High levels of PCB contamination have migrated into the floor drain; and
- 3. The dust generated during the concrete removal appears to have spread the contamination further.

The soil cleanup guideline for PCB contamination in restricted access areas is 25 ppm.

The cleanup level for indoor surfaces in restricted access areas is 10 ug/100 cm² in the standard wipe test) or 100 ug/100 cm² followed by encapsulation (40 CFR Part 761.60, Section IV--Requirements for PCB Spill Cleanup, Subsection C, requirements for cleanup of high-concentration spills and low concentration spills involving 1 pound or more PCBs by weight).


The EPA Region VII has not looked favorably upon the encapsulation option recently due to extensive migration of PCBs through concrete.

No question should remain, that further remediation is required at the subject site. The area should be considered a hazardous waste site and access should be strictly limited.

A human health threat exists in the form of human contact with, and inhalation of, high concentration PCB contaminated dust. The 10-hour time weighted average exposure limit established by NIOSH is 1.0 ug/m³ (NIOSH Guide to Chemical Hazards, U.S. Department of Health and Human Services, 1985). The dust sample collected showed 31.0 ug/100 cm². Polychlorinated biphenyls are listed as a known carcinogen with inhalation, skin absorption, ingestion, skin, and/or eye contact as routes of entry. A strong possibility exists for the further spread of the contamination by human or vehicle traffic. The contamination could also be carried offsite on worker clothing.

It cannot be over emphasized that the area should be sealed and access be allowed only to personnel with appropriate training and protective equipment.

		_
		,



:TCH MAP

CARBURETOR - 2800 NORTH SPRING

"= 10'

WIPE SAMPLING POINT

ENTRATION OF PCB U9's/100 cm²

3-1



Environmental Science & Engineering, Inc.

APPENDIX A

Environmental Operations, Inc.'s Initial Study

		_

22x-.002 1

ENVIRONMENTAL

ODERATIONS, INC.

HABARDOUS WASTE AND UNDERGROUND TANK MANAGEMENT

905 PARK AMALE ST LOCK NO 63 14 (314) 231-8226

January 26, 1989

Project #2285

Mr. Hugh Thompson P.O. Box 63163 St. Louis, MO 63163

Mr. Thompson:

This letter is to transmit results of samples collected by Environmental Operations, Inc. and analyzed by Environmetrics, Inc. for Polychlorinated Biphenyls (PCB's) content. The samples were collected by Bill Atkins of Environmental Operations, Inc. on January 16, 1989 at the old Carter Carbaretor facility located at the corner of Grand and St. Louis, Ave.

The purpose of the sampling was to determine if releases had occurred from six high level transformers located on the ground level of the facility and four high level transformers located outside the facility facing Grand Avenue. Also located next to the interior transformers were 16 oil cooled circuit breakers with unknown PCB concentrations. The interior area will be referred to as Bank 2, the exterior as Bank 1.

Samples were collected from areas which visually appeared to have been stained with oil. The samples were collected by first applying hexane to a piece of of filter paper and thoroughly rubbing this moistened paper over a 100 sq. cm. area of the sample surface (delineated by a template). The filter was immediately placed in a sample bottle which was then tightly capped and labeled.

		•
		,

The results are as follows:

Sample f	Location	Total-micrograms/100 CK2
2285.1	Bank 2 - Southeast	106,071 fairly high. Direct h
2285,2 Thener	Bank 2 - Central West	3,300
2285.3 Commissioners located	Bank 2 - Central West Bank 2 - North, underneath circuit breaker	660 (Cleanup.
2285.4	Bank 2 - Central East	1,5.55)
2230.5 Outside Sampling	Bank 1 - South pad western transformer	<2

A rough sketch of sample locations is attached.

The Environmental Protection Agency (EPA) PCB Spill Clean-up Policy may be found in the Federal Register, Part III, 40 CFR Part 761, issued April 2, 1987. A copy of this regulation is enclosed.

Immediate (48 hours) requirements include (see 40 CFR Part 761 Unit III.C):

- Notification of the EPA regional office and the NRC
- Restrict access to area
- Record and document spill area
- Initiate clean-up

Bank 2 would appear to be a low contact, indoor, non impervious surface, which is addressed in Unit IV,C.3.c. This section states clean up standards of 10micrograms/100cm², or 100micrograms/100cm² and encapsulation.

It should be noted that the samples were collected by selecting a sampling surface which appeared to be worst case. No effort was made to identify contamination boundaries or to estimate volumes of material which would need to be removed to meet the clean up standards. To obtain this information a statistically based sampling scheme should be developed.

Any questions regarding this report may be directed to Bill Atkins or myself at 231-8226.

sincerely,

Rose P. Aberra

Roger R. Hopson Prenident

Enclosures

cc Skip Colburn

		<u></u>
		_
		_

ENVIRONMENTAL OPERATIONS 905 PARK AVENUE ST. LOUIS, MO 63104

ENVIRONMETRIC

10679 Midwest Industrial B St. Louis, MO 63 (314) 427-0:

JOB #2285

ANALYSIS REPORT

PCBS IN SWABS

SAMPLE NO.	<u>IDENTIFICATION</u>	TOTAL ug 100 cm²	TYPE
2285-1		106,071	1260
2285-2		3,300	1260
2285-3		660	1260
2285-4		1,555	1260
2285-5		<2	

JANUARY 24, 1989

WAYNE L. COOPER LABORATORY DIRECTOR

ij,

		,
		_
	•	
	٠	
		, and a

ENVIRONMENTAL OPERATIONS 905 PARK AVENUE ST. LOUIS, MO 63104 ENVIRONMETRIC:

10679 Midwest Industrial Blv St. Louis, MO 631 (314) 427-05

JOB #2285

ANALYSIS REPORT

197

PCBs IN SWABS

	<u>IDENTIFICATION</u>	TOTAL UG 100 cm²	TYPE
SAMPLE NO.		106,071	1260
2285-1		3,300	1260
2285-2 2285-3		660	1260
-		1,555	1260
2285-4		<2	
2285-5			

JANUARY 24, 1989

WAYNE L. COOPER LABORATORY DIRECTOR

		_
		_
		-

- -

_

APPENDIX B

USEPA Letter Concerning MDNR Inspection

		_



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VII 726 MINNESOTA AVENUE KANSAS CITY, KANSAS 66101

June 7, 1989

James C. Owen, Esq. Emerald Point 16141 North Outer Forty Drive, Suite 300 St. Louis, MO 63017

Dear Mr. Owen:

RE: Hubert Thompson TSCA No. VII-87-T-719

An inspection of Mr. Thompson's facility was conducted by Missouri Department of Natural Resources inspector Robert Krager on February 21, 1989. As part of that inspection he took a soil sample from the area where the concrete pad had been removed. Results of the sample analysis showed the presence of 1200 ppm PCB in said soil sample.

Please advise as to what has been done to address clean up of this area. I would appreciate hearing from you as soon as possible, so that we can conclude this case.

Sincerely,

Henry F. Rompage

Attorney

Office of Regional Counsel

Hanny Fo Rompous

		_

APPENDIX C

Laboratory Data from the Environmental Operations, Inc.
Remediation Verification Study

ENVIRONMENTAL OPERATIONS 2649 PESTALOZZI STREET

ST. LOUIS, MO 63118

ATTENTION: BILL ATKINS

INVOICE: #6708

ENVIRONMETRICS

2345 Millpark Drive Maryland Height St. Louis County, MO 63041

(314) 427-0550

ANALYSIS REPORT

PCBs IN SOIL

SW-846 8080

	<u>SAMPLE</u>	<u>IDENTIFICATION</u>	TOTAL DDM	TYPE
7		10 pt eans. 2285.A '	167	1260
I	et northermost	10 pt long. 2285.B	209	1260
 		2285.X	<2	

NOVEMBER 16, 1989

WAYNE L. COOPER LABORATORY DIRECTOR

			_
			•
			,

ENVIRONMETRICS

2345 Millpark Drive Maryland Heights St. Louis County, MO 63043 (314) 427-0550

ENVIRONMENTAL OPERATIONS 2649 PESTALOZZI STREET ST. LOUIS, MO 63118

ATTENTION: BILL ATKINS

INVOICE #6708

ANALYSIS REPORT

PCBs IN SWABS


SW-846 8080

	TDE	NTIFICATION	TOTAL 2	TYPE
SAMPLE. I	No	2285.C	2,823	1260
y ps	Ecart	2285.D	2,286	1260
3,0e.ls 2	00	2285.E	449	1260
3	went	2285.F	5,407	1260
full ble	in b	2285.Y	<2	

NOVEMBER 16, 1989

WAYNE L. COOPER LABORATORY DIRECTOR

		_ ;
		,



			<u> </u>
)

APPENDIX D Laboratory Data from EPA Sampling

L

				_
				_



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VII 726 MINNESOTA AVENUE KANSAS CITY, KANSAS 66101

May 16, 1990

James C. Owen, Esq. Emerald Point 16141 North Outer Forty Drive Suite 300 St. Louis, MO 63017

Dear Mr. Owen:

Enclosed as you requested, are the sample analysis results for the Thompson property.

Sincerely,

Hangto verysey

Henry F. Rompage

Attorney

Office of Regional Counsel

Enclosure

		-	
. 1			
			_
			_
			_
			_
			_
			_
			_
			_

ANALYSIS TYPE: PCB DATA HATRIX: CONTROL BUTTLE UNITS: UG/BHPL EI HUBERT THOMSON EPA REGION VII METHOD: 8701M70 CASE:
SAMPLE PREP! DATE: 04/24/90 DATA FILE: SBM SLA74001F .30U PCB1221 .100U CB1232 JANKERSHE .4QU PCB1016 or . 400 .40U . .1000 CB1240 HEANS NOT ANALYZED **

7	
	-
	•

-USEFA EDV

```
E: HUBERT THOHSON

EPA REGION VII

SAMPLE PREP: _____ ANALYST/ENTRY: SBM REVIEWER: _____ DATE: 04/24/90
                                                                                                                                                                                                                                                                                  DATA FILE: SBM
                                                                                                                                                                                                                                   SLA74002 SLA74003
                                                                                                                                                                                                                                                                                                                                                                                                        5LA74004
                                                                                                                                                                                                     2000.U

1000.U

3000.U

3000.U
      CB1221
CB1016 or CB1242 PCB1248 PCB1254 PCB1250
  CB1248
CB1254
CB1260

(SGL)
CSGL)

XX NOTE: N/A "MEANB NOT ANALYZED XX
I MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX

XX NOTE: N/A "MEANB ANALYZED BUT INVALID DATA XXX
```

		<u> </u>
		<u> </u>
		-

0132302834pi-udera edu - 5-10-50 + 10-47 + ARTXI# 4 ANALYSIS TYPE: PCB DATA ITLE: HUBERT THOMSON HATRIX: WIPES UNITS: UB/EMPL HETHOD: B701H70 CABE: LAB: EPA REGION VII SAMPLE PREP: ____ ANALYST/ENTRY: SBM REVIEWER: DATE: 04/25/90 DATA FILE: SBM 8LA74005Fd6 SLA74006 . BLA74007 1500.U 150.U 50.U , 30U CB1221 ,100U 500.U CB1232 . 40U 2)200.U)2000.U CB1016 or 200.U , 40U CB1242 200.U 2000.0 . 40U CB1248 .40U 2000.U 200.U CB1254 5600. ,100U \820. (wipe) Temipe Y * THOTE! THYA HEANS NOT ANALYZED ** INOTE 1 N/A MEANS NOT ANALYZED BUT INVALID DATA ***

APPENDIX E

Waste Advisory, Inc. Report

June 20, 1990

Mr. Todd Massa, Atty.
Buechner, McCarthy, Leonard
Kaemerer, Owen & Laderman
16141 N. Outer Forty Drive, Ste 300
St. Louis, MO 63017

Dear Mr. Massa:

Jim Owen instructed me to submit this report and proposal on the Hugh Thompson Space Center PCB Clean Up Project to you:

Scott George, presently of Brucker Engineering & Assoc., and I examined the site on the 11th of June, took three samples to establish presence of PCBs in concrete adjacent to the area removed and had them tested. Results with this letter.

We, Waste Advisory, then consulted with Environmental Operations, who has represented the bank (Boatmen's) and has done some sampling and testing of their own. They were kind enough to give us their field sampling sketch and results.

We also spoke with Doug Elders, of the USEPA, who said his agency would like to see Mr. Thompson characterize the PCB contamination thoroughly. He doesn't believe a great many tests would be necessary. He has special concern about the area around the drain and the periphery of the excavated area where the transformers stood.

He also exhibited some concern about general surface contamination from the dust created by the concrete removal that was done earlier by Hugh Thompson.

We discussed encapsulation. He said that really was not an option the EPA could buy in light of its past experience with PCBs migrating through thick sections of concrete.

That same characteristic, especially to be feared in the case of old spills, may make solvent cleaning impractical also. He reports the EPA experience with acid/solvent cleaning to be a mix of success and failure. Failure is usually the result of the high relative permeability of the surface cleaned and age of spill. Deeper contamination means less effective cleaning.

We concluded the EPA would respond favorably to a well-supported, practical site characterizing plan and removal. Whatever is done, according to Mr. Elders, the result must be a clean site.

Accordingly, we asked Scott George to put together a proposal for preliminary site characterization. A copy is enclosed for your examination. Whether Brucker Engineering or Scott's new employer, Environmental Science & Engineering, does the work, the estimated costs will be the same. (My confidence is in the individual, Scott George.)

Once this work is done, we will be in a much better position to identify method and cost of remediation.

We will await your approval before proceeding.

Respectfully submitted,

Wilson M. Powell, CHMM

encl/Brucker proposal Test results Invoice #369

cc/S. George

		_

ENVIRONMETRICS

2345 Millpark Drive Maryland Heights, MO 63043 (314) 427-0550

WASTE ADVISORY, INC. 135 W. ADAMS KIRKWOOD, MO 63122

ATTN: WILSON M. POWELL

INVOICE # 8910

ANALYSIS REPORT

PCBs IN SOLID

SW-846 8080

SAMPLE #	<u>IDENTIFICATION</u>	TOTAL ppm	TYPE
	1	225	1260
	2	197	1260
	3	82	1260

JUNE 5, 1990

WAYNE L. COOPER
LABORATORY DIRECTOR

•			
			_
			_
			4
			,
			,
			,
			,

APPENDIX F Laboratory Report from the ESE Study

,



TO: Scott George

FROM: John Gemoules

SUBJECT: Analytical Results for Soil Samples,

Waste Advisory, Inc.

Nineteen (19) wipe, one (1) oil, and one (1) water samples were received in the ESE St. Louis Chemistry Laboratory on September 7, 1990, for PCB analyses. The analyses were performed in accordance with the following methods:

Malysis Method Uni	
PCBs, wipe GC/ECD ug-	otal
PCBs, oil GC/ECD mg/	(g
PCBs, water 8080 ug/	L

A quality control (QC) summary is included in this report. The QC samples analyzed with these samples indicate there were no technical problems with the analyses.

The following are the results for the above mentioned samples.

JFG/p1/REPORT/WAI.RP

--- .

		_
		,
		_
		_
		_

SECTION 1

Analytical Results

		_
	·	

 € ENCINEERING
 INC.

 € ENCINEERING
 INC.

 € ENCINEERING
 INC.

 ENCERNA
 INC.

PROJECT NUMBER: SCOTT GEORGE PRICT/NASTE ADVISORY, INC.

SAMPLE HATREX: JUHPE PROJECT MANACER: JOHN F GENOULES

CRIR CH-8	(RIR CH-7	CRIR CH-6	CRIR CH-5	CRTR CH-4	CRTR CH-3	CRIR CH-2	CRTR CM-1			SAMPLE 1.D.
8 - 1 AM	(+ I A H	9+1 VM	SHIMM	P # I AU	E+IVM	SHIAW	1 = 1 A N			.0.1 84.1
06/90/60	06/90/60	06/90/60	06/90/60	06/90/60	06/90/60	06/90/60	06/90/60			COLLECTION DATE
								STINU	RABER CAS NUMBER	83T3MARA9
0165	0.1452	0125	0.452	424.0	<24.0	084>	0.45>	วก	2-11-1/921	PCB-1016
<540	0.1452	012>	<24.0	<24.0	0.45>	084>	0.45>	ne	11104-28-2	PCB-1221
(540)	01#2>	<540	<24.0	0.45>	0.15>	084>	6.45>	วก	S-91-1111	PCB-1232
0525	01425	<510	0.45>	<24.0	<24.0	084>	0.45>	วก	6-12-69125	PCB-1242
01675	0.323	012>	<24.0	424.0	0.42>	084>	0.45>	nc	9-62-21921	PCB-1248
6540	0.452	n#Z>	424.0	<54.0	0. \$2>	084>	0.45>	ne	1-69-26011	PCB-1254
0222	1776	0611	061	SES	1.44	E # 7	E , 25 . 3	ne	5-28-96011	PCB-1260

				/

09-21-1990

TATUS: FINAL

PAGE# 2

PROJECT NAME: SCOTT GEORGE PRICT/WASTE ADVISORY, INC.

PROJECT NUMBER. 5902020 0136

FIELD GROUP: HAT

SAMPLE MATRIX: WIPE

.

PROJECT MANAGER: JOHN 1. GEMOULES

CONCENTRATION

SAMPLE 1.D.			CRTR CH-9	CRTR CH-10	CRTR CH-11	CRTR CH: 12	CRTK CH- 13	CRTR CH-14	CETE CH 15 HA1+15	CRIR CH-16 HAI+16
COLLECTION DATE			09/06/90	09/06/90	09/06/90	09/06/90	09/06/90	09/06/90	09/06/90	09/06/90
PARAMETER	CAS NUMBER	21140								
PCB-1016	12674-11-2	uc	<24.0	<240	<24.0	₹240	<24.0	<24.0	₹24 0	<240
PCB-1221	11104-28-2	UG	C24 . 0	<240	(24.0	<240	<24.0	<24.0	₹240	₹240
PCB-1232	11141-16-5	UG	<24.0	<240	<24.0	<24u	<24.0	<24.0	<240	<240
PCB-1242	53469-21-9	UG	<2 4 .0	<240	<24.0	₹240	<24.0	₹24.0	<240	\$240
PCB-1248	12672-29-6	UC	<24.0	<240	<24.0	(240	(24.0	₹24.0	3246	₹240
PCB-1254	11097-69-1	UG	<24.0	<240	<24.0	<240	<24.0	\$24.0	0140	4240
PCB-1260	11096-82-5	UG	620	379	191	54.7	32 4	14.5	: 3 n	14.

•

		_'

09-21-1990

TATUS: FINAL

PAGE# 3

PROJECT NAME:

SCOTT GEORGE PRUCT/HASTE ADVISORY, INC.

PROJECT NUMBER: \$902020 0136

FIELD GROUP: WAT

SAMPLE MATRIX:

HIPE

PROJECT MANAGER; JUHN 1. GEMOULES

CONCENTRATION

SAMPLE 1.D.			CRTR CH-17	DUST HIPE	BL ANN
LAB I.D.			WA1*17	NA 1 = 18	WA1*20
COLLECTION DATE			09/06/90	09/06/90	09/06/90
PARAMETER	CAS NUMBER	UNITS			
PCB-1016	12674-11-2	UG	<120	<24.0	<2.40
PCB-1221	11104-28-2	UG	<120	<24.0	<2.40
PCB-1232	11141-16-5	UG	<120	₹24.0	<2.40
PCB-1242	53469-21-9	UG	<120	<24.0	<2.40
PCB-1248	12672-29-6	UG	<120	<24.0	<2.40
PCB-1254	11097-69-1	UG	<120	<24.0	<2.40
PCB-1260	11096-82-5	UG	213	31.0	<2.40

		_
		_

09-21-1990

US: FINAL

PAUL# 4

PROJECT NAME:

SCOTT GEORGE PRUCT/HASTE ADVISORY, INC.

PROJECT NUMBER: 5902020 0136

FIELD GROUP: HAT

SAMPLE MATRIX: HIPE

PROJECT MANAGER: JOHN F. GEMOULES

CONCENTRATION

SAMPLE I.D.			ASBESTOS
LAB I.D.			HA1+19
COLLECTION DATE			09/06/90
PARAMETER	CAS NUMBER	STINU	
PCB-1016	12674-11-2	MG/KG-OIL	C1.00
PCB-1221	11104-28-2	MG/KG-OIL	<1.00
PCB-1232	11141-16-5	MG/KG-OIL	<1.00
PCB-1242	53469-22-9	MG/KG-OIL	<1.00
PCB-1248	39500*SECO	MG/KG-OIL	<1.00
PCB-1254	11097-69-1	MG/KG-OIL	<1.00
BSD 1040	1100/ 02 5	MO 4110 O.L.	71. O.O.
PCB-1260	11096-82-5	MC/KC-OIL	<1.00

				_ "
	•			

09-21-1990

ATUS: FINAL

PAGE # 1

PROJECT NAME:

SCOTT GEORGE PRUCT/WASTE ADVISORY, INC.

PROJECT NUMBER: 5902020 0136

FIELD GROUP: HAT-H

SAMPLE MATRIX:

WATER

PROJECT MANAGER: JOHN F. GEMOULES

CONCENTRATION

SAMPLE 1.D. LAB 1.D. COLLECTION DATE			CRIR DRN WAI-HMI 09/06/90
PARAMETER	CAS NUMBER	UNITS	
PCB-1016	12674-11-2	UC/L	< 650
PCB-1221	11104-28-2	UG/L	<650
PCB-1232	11141-16-5	UG/L	<650
PCB-1242	53469-22-9	UG/L	<650
PCB-1248	12672-29-6	UG/L	₹650
PCB-1254	11097-69-1	UG/L	₹€50
PCB-1260	11096-82-5	UG/L	1620000

		_	
		_	

SECTION 2

QC Summary

		_
		_

↓AME	UNITS	STOR*METH	BATCH	SAMPLE	DATE	ربا
'CB-1016	UG	34671*WIPE	\$3868	MB*NONE * 1	09/14/90	
'CB-1221	UC	39488#WIPE		MB*NONE * 1		
³CB-1232	UG	39492*WIPE		MB*NONE * I		Ú.u
PCB-1242	UG	39496*WIPE		MB # NONE # I		0.0
PCB-1248 .	UG	39500*WIPE		MB * NONE * I		0.0
PCB-1254	UG	39504*WIPE		MB = NONE = I		0.0
PCB-1260	UG	39508*HIPE		MB * NONE * 1		0.0

Standard Matrix Spike Recovery and Replicate Summary

NAME	UNITS	STOR#METH	BATCH	SAMPLE	DATE	TARGET	FOUND	≭ RE C V	RECV CRIT	R.P.D.	R.P.D. CEIT
PCB-1016	UG	34671*HIPE	23868	SPI#NONE#1	09/14/90	5.00	5.28	106	70-125		25
PCB-1016	UG			SP2*NONE*I		5.00	5.93	119	70-125	11.6	25
PCB-1260	UG	39508*WIPE		SP I * NONE * I		10.0	9.84	98.4	30-130		50
PCB-1260	UG			SP2#NONE#1		10.0	11.5	115	30-130	15.6	50

f

		_
		_

NAME	4000					
PCB-1016	UG/L	34671#SEC	S3867	MB*NONE * I	09/14/90	nυ
PCB~1221	UG/L	39488*SEC		MB*NONE * I		
PC8-1232	UG/L	39492*SEC		MB*NONE * 1		
PCB-1242	UG/L	39496*SEC		MB#NONE # I		
PCB-1248	UG/L	39500#SEC		MB*NONE #1		0.0
PCB-1254	UG/L	39504*SEC		MB*NONE * I		0.0
PCB-1260	UG/L	39508*SEC		MB * NONE * I		50.4

Standard Matrix Spike Recovery and Replicate Summary

NAME	UNITS	STOR*METH	BATCH	SAMPLE	DATE	TARGET	FOUND	≭ RE C∨	RECV CRIT	<u>F P</u> . D.	R.P.D. CEIT.
PCB-1016	UG/L	34671*SEC	\$3867	SPI *NONE * I	09/14/90	120	136	113	58-130		25
PCB-1016	UC/L			SP2*NONE * I		120	106	88.3	58-130	24.5	25
PCB- 1260	UG/L	39508*SEC 1		SPI*NONE * 1		250	297	119	30-130		50
PCB-1260	UG/L			SP2*NONE * I		250	150	59.8	30 - 130	66.2	50

			_

SECTION 3

Chain of Custody

		_
		·

ENVIRON PAL SCIENCE AND ENGINEERING, INC. PROJECT NUMBER:

THE PROPERTY OF THE PARTY OF THE

09-L 0

FIELD GROUP: WAI-W

PROJECT NAME: SCOTT GEORGE PRJCT/WASTE ADVISORY, INC.

COLLECTION COLLECTION HAZARD SAMPLE I.D. ESE # FRACTIONS (CIRCLE) CODE DATE TIME (Only the first 10 Char. will be used) EC EC EC WAI-W*1 · Carritier Diriaini NOTE -PLEASE ENTER SAMPLE ID; UP TO 10 ALPHANUMERIC CHARACTERS MAY BE USED.
-CIRCLE FRACTIONS COLLECTED. ENTER DATE, TIME, FIELD DATA (IF REQUIRED), HAZARD CODE AND NOTES
-HAZARD CODES: I-IGNITABLE C-CORROSIVE R-REACTIVE T-TOXIC HASTE H-OTHER ACUTE HAZARD; IDENTIFY SPECIFICS IF KNOWN
-PLEASE RETURN LOGSHEETS WITH SAMPLES TO ESE RECEIVED BY (NAME/ORGANIZATION/DATE/TIME) RELINQUISHED BY: (NAME/ORGANIZATION/DATE/TIME) OTHER FIELD NOTES FOR FIELD GROUP WAI-W: LAB NOTES: Could not fill all 3 bottles jers you must fill "3" bothers for one sample.

PLEASE INITIAL IF YOU HAVE RECEIVED AND READ THE ENCLOSED INSTRUCTION SHEET

			_
			-

ENVIRON 'AL SCIENCE AND ENG. ERING, INC. PROJECT NUMBER:

ESE #	FRAC	TIONS (C		HAZARD CODE	COLLECTION DATE	COLLECTION TIME	SAMPLE I.D. (Only the first 10 Ch	nar. will be used)
WAI*1	CB 1	Nice 1	(5)	T	916190	10:30	Carters	W ₁ -11,
WAI*2	1				916190	10:40		1-131
WAI*3					916190	10:50		1-131
WAI*4					916190	16:00		1-141
WAI*5					916190	ll:10	1 1 1 1 1 1 1	1-151
WAI*6					916190	11:20		1-161
WAI*7					916190	<i>l</i> (:30		1-171
WAI*8					916190	11:40	1 1 1 1 1 1 1	1-181
WAI*9					916190	11:50		1-191
WAI*10					916190	13:00		1-1/01
WAI*11					91670	12:10		1-111
WAI ± 12					916190	12:20		1-112
WAI * 13					916190	12:30		1-1131
WAI * 14		1,	1	7.	916 190	12:40	1 1 1 1	. 1-1141
WAI*15	$\overline{\Psi}$	V	U	V	916190	12:50		1-151
					ALPHANUMERIC DATE, TIME, F TIME T-TOXIC WASTE H PLES TO ESE ON/DATE/TIME)		MAY BE USED. F REQUIRED), HAZARD CODE IDENTIFY SPECIFICS IF KNOWN ELIVED BY (NAME/ORGANIZ	
						~~~~~~~~~~		
2	BE	Dag /	636	11_	-9 <u>0</u>	X s	ESE 9-7-50	.58 <del>.7</del> 4
OTHER FIE	LD NOTES	FOR FIE	D GROU	P WAI:	<del>-</del>			
LAB NOTES		YOU HAVE	RECEIV	ED AND	READ THE ENC	LOSED INSTRU	CTION SHEET	

		-

AND ENG TERING, INC.
PROJECT IBER:

WAI #20

09-05 70

PROJECT NAME: SCO?

J FIELD GROUP: WAI EORGE PRJCT/WASTE ADVISORY, INC.

HAZARD COLLECTION COLLECTION SAMPLE I.D. (Only the first 10 Char. will be used) ESE # FRACTIONS (CIRCLE) CODE DATE TIME WAI * 16 13:00 Clairitie Mc.IWI-1/61 **WAI** * 17 13:10 NOTE -PLEASE ENTER SAMPLE ID; UP TO 10 ALPHANUMERIC CHARACTERS MAY BE USED.
-CIRCLE FRACTIONS COLLECTED. ENTER DATE, TIME, FIELD DATA (IF REQUIRED), HAZARD CODE AND NOTES -HAZARD CODES: I-IGNITABLE C-CORROSIVE R-REACTIVE T-TOXIC WASTE H-OTHER ACUTE HAZARD; IDENTIFY SPECIFICS IF KNOWN -PLEASE RETURN LOGSHEETS WITH SAMPLES TO ESE RECEIVED BY (NAME/ORGANIZATION/DATE/TIME) RELINOUISHED BY: (NAME/ORGANIZATION/DATE/TIME) eng ESE 9-7-90 2 Vant ESE 9-7-90 0824 OTHER FIELD NOTES FOR FIELD GROUP WAI: LAB NOTES: lease add: PCB Dust Wipe 9-6-90 - 13:20 Asbestos Gb. 9-6-90 - 13:30 WAI * 19

PLEASE INITIAL IF YOU HAVE RECEIVED AND READ THE ENCLOSED INSTRUCTION SHEET

9-6-90

		_
		-
		-

# APPENDIX G

Site Photographs from the ESE Study

				_
				_
			•	
	,			



1. Standard Wipe Test, Sampling Location #2.



2. Study area looking north showing the concrete removal section and sampling point 12.